


Modario

Tragschiene


Trunking rail

5TR1...




53BM...

siteco




5TR9 . 1312 5TR9 . 1332 ➔ 	5LY9001 5LY9002 ➔ 	5TR901342 ➔ 	
5TR9012 ➔ 	5TR901302 ➔ 	5TR901322 ➔ 	
5LS91101EA ➔ 	5TR9013 . ➔ 	5TR90142 ➔ 	5LY9004 ➔

5TR9016 . ➡  




1x 2x

5TP9016 ➡  




1x 2x

5TR91AFN0 ➡ 




1x
1x
2x

5TR910FNKA ➡ 





9...11
1.5...2.5mm²
9...11
5

5TR910FNKAF ➡ 




10x 2.5mm²
9...11
1.5...2.5mm²
9...11
5


1x 1x




	1 L1	2 L2	3 L3	N	PE	PE	4 N'	5 DA+	6 L'	7 DA-	WH L''	BU N''
5TR1 .. 0 ..												
5TR1 .. 5 ..	X	X	X	X	X							
5TR1 .. 7 ..	X	X	X	X	X			X		X		
5TR1 .. A ..	X	X	X	X	X	X	X	X	X	X		
5TR1 .. C ..	X	X	X	X	X	X	X	X	X	X	X	X




- 1** Umgebungstemperatur während der Installation: +5°C...+40°C
Ambient temperature during installation:



- 2**
-
- T25



3 53BM...




5TR91AFTC ➡ 

1x


1x

1x






5TR910FTKAF ➡ 




1x

1x




10x 2.5mm²



 >PA<

00000000000000

1 2 3 N  4 5 6 7




9...11

9...11



1.5...2.5mm²


5





7


siteco











5MA11-267808_af
04.12.2025 / PZ

Siteco GmbH
Georg-Simon-Ohm-Straße 50
83301 Traunreut, Germany
mail: technicalsupport@siteco.de
Phone: +49 8669 / 33-844
www.siteco.com